

SDMS US EPA REGION V -1

**SOME IMAGES WITHIN THIS
DOCUMENT MAY BE ILLEGIBLE
DUE TO BAD SOURCE
DOCUMENTS.**

MASTER STATUS LIST
IEPA SCRAP SITE INVESTIGATIONS FOR MERCURY REGULATORS
(9/27/00)

1	Chicago Heights Iron and Supply	1715 Wentworth Avenue	Nicor	9/1/2000	Regulators present and Mercury detected.	488 regulators separated from scrap and soil. Cleanup of extensive soil contamination is continuing (oversight by USEPA).
2	Archer Metal (a/k/a C&R Scrap)	4619 South Knox, Chicago	Nicor	9/2/2000	No regulators observed. No Mercury detected.	No anticipated action.
3	Bertinsky Scrap	212 Page Avenue, Joliet	Nicor	9/2/2000	Regulators present and Mercury detected.	Cleanup plan being developed (oversight by USEPA).
4	G and D Salvage	104 West Lincoln, Loda	Nicor	9/2/2000	No regulators observed. No Mercury detected.	No anticipated action.
5	General Iron	1901 North Clifton, Chicago	Nicor	9/2/2000	No regulators observed. No Mercury detected.	No anticipated action.
6	United Scrap	1545 South Cicero Avenue, Cicero	Nicor	9/2/2000	No regulators observed. No Mercury detected.	No anticipated action.
7	Ace Iron	11th Third Avenue, Joliet	Nicor	9/5/2000	No regulators observed. No Mercury detected.	No anticipated action.

141716

					No regulators observed. No Mercury detected.	No anticipated action.
8	Behr Iron and Steel	1100 Seminary, Rockford	Nicor	9/5/2000	Mercury detected.	No anticipated action.
9	Belson Scrap	1685 North State, Bourbonnais	Nicor	9/5/2000	No regulators observed. No Mercury detected.	No anticipated action.
10	Buchman Iron	705 5th Street, Mendota	Nicor	9/5/2000	No regulators observed. No Mercury detected.	No anticipated action.
11	Buckman	153 Canal Street, LaSalle	Nicor	9/5/2000	No regulators observed. No Mercury detected.	No anticipated action.
12	DeKalb Iron and Metal	900 Oak, DeKalb	Nicor	9/5/2000	Regulators present and Mercury detected.	Cleanup plan being developed (oversight by USEPA).
13	Elgin Recycling and Salvage	533 North State, Elgin	Nicor	9/5/2000	No regulators observed. No Mercury detected.	No anticipated action.
14	Elgin Salvage and Supply	465 McBride, Elgin	Nicor	9/5/2000	No regulators observed. No Mercury detected.	No anticipated action.
15	Morris Tick Company	501 East Stewart, Bloomington	Nicor	9/5/2000	No regulators observed. No Mercury detected.	No anticipated action.
16	Newton Iron	901 West Marquette St., Ottawa	Nicor	9/5/2000	Regulators present and Mercury detected.	Cleanup plan being developed (oversight by USEPA).
17	Sinow and Wienman	78 Monroe Avenue, Dixon	Nicor	9/5/2000	No regulators observed. No Mercury detected.	No anticipated action.

Oct-03-2000 08:56am From-EPA CHEMICAL SAFETY

217-524-4036

T-778 P.003/005 F-156

18	Cozzi Iron and Metal	3151 South California, Chicago	Nicor People's	9/8/2000	Trace Mercury found on conveyor belt of crusher. No regulators observed.	No anticipated action.
19	Cozzi Metal	2200 South Paulina St., Chicago	Nicor People's	9/8/2000	No regulators observed. No Mercury detected.	No anticipated action.
20	John Hierz	Verona	Nicor	9/12/2000	No regulators observed. No Mercury detected.	No anticipated action.
21	Reserve Iron and Metal	12701 South Doty, Chicago	Nicor	9/12/2000	No regulators observed. No Mercury detected.	No anticipated action.
22	Austeel	Lemont	Nicor	9/12-13/2000	Traces of Mercury found on scrap that goes to arc furnace.	Samples of dust from air pollution equipment taken by IEPA.
23	A. Miller & Corporation	1612 Southwest Adams Street, Peoria	Nicor	9/21/2000	No regulators observed. No Mercury detected.	No anticipated action.
24	Pontiac Recyclers, Inc.	1703 North Aurora Street, Pontiac	Nicor	9/21/2000	No regulators observed. No Mercury detected.	No anticipated action.
25	Groeling Salvage Service	220 E. Exchange, Freeport	Nicor	9/22/2000	No regulators observed. No Mercury detected.	No anticipated action.
26	Harris Silver & Sons	800 East Pleason Street, Belvidere	Nicor	9/22/2000	No regulators observed. No Mercury detected.	No anticipated action.

27	Mercury Waste Solutions	21211 Durand Avenue, Union Grove, WI	Nicor	9/22/2000	Received regulators with Mercury from Nicor for processing in Mercury retort to separate and recover Mercury.	IEPA took samples.
----	-------------------------	--------------------------------------	-------	-----------	---	--------------------